

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080022-9

No. 11253

RECEIVED FROM

2961 E. COLORADO ST., PASADENA, CALIF.

PLATE #9

DATE REC'D. 2-12-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	S.O. NO.
	322			24	0	10				

DRAWING NO. AND DESCRIPTION

QUANTITY
ACCEPTED REJECTED

REMARKS

3 731441 Harness Asbly

3 ✓

Shipped 2-12-57

W.E. Kunkle
J.L. HendleyRECEIVED
BYINSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11254

RECEIVED FROM

PLATE #9

DATE REC'D. 2-12-57
P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	S.O. NO.
	322			24	0	10				

DRAWING NO. AND DESCRIPTION

QUANTITY
ACCEPTED REJECTED

REMARKS

3 731341 Socket, Vise Number

3 ✓

Rejected 3/12/57

Shipped 2-12-57

W.E. Kunkle
J.L. Hendley

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080022-9

RECEIVED
BY

HMC-1969

INSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.